

This certifies that the Quality Management System of

K&S Servicios Industriales SA de CV

Orion 1463 Int 1 Parque industrial Orion, C. P. Apodaca, Nuevo Léon, 66600, Mexico

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

ISO 9001:2015

Scope of Certification:

Repair of electronic, mechanical and electromechanical industrial equipment.

Sameer Vachani

Senior Director, NSF-ISR

Certificate Number:48761-IS6Certificate Decision Date:10-APR-2024Certificate Issue Date:10-APR-2024Cycle Effective Date:20-FEB-2023Certificate Expiration Date*:19-FEB-2026







ANNEX PAGE FOR CERTIFICATE NUMBER: 48761-IS6

This Annex is only Valid in connection with the above-mentioned certificate issued by NSF-ISR

CERTIFICATE ISSUE DATE: 10-APR-2024 CERTIFICATE EXPIRATION DATE: 19-FEB-2026

K&S Servicios Industriales SA de CV Orion 1463 Int 1 Parque industrial Orion, C. P. Apodaca, Nuevo Léon, 66600, Mexico Location:

K&S Servicios Industriales SA de CV- C0274847 Libramiento Politecnico 116 Salamanca, Guanajuato, 36872, Mexico Scope:

This location is part of site 48761. Supporting processes include: Repair of electronic and electromechanical industrial equipment.

Issued by: NSF International Strategic Registrations (NSF-ISR) 789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.





